

## Gravatt, Dan

---

**From:** Nagel, Chris [Christopher.Nagel@dnr.mo.gov]  
**Sent:** Monday, March 18, 2013 9:16 AM  
**To:** Gravatt, Dan; Muenks, Shawn  
**Cc:** Tapia, Cecilia  
**Subject:** RE: West Lake Landfill: air compliance inspection report

Thanks Dan.

Chris Nagel  
Director  
Solid Waste Management Program  
Missouri Department of Natural Resources  
(573) 526-3900  
(573) 526-3902  
[chris.nagel@dnr.mo.gov](mailto:chris.nagel@dnr.mo.gov)

---

**From:** Gravatt, Dan [<mailto:Gravatt.Dan@epa.gov>]  
**Sent:** Friday, March 15, 2013 12:05 PM  
**To:** Nagel, Chris; Muenks, Shawn  
**Cc:** Tapia, Cecilia  
**Subject:** West Lake Landfill: air compliance inspection report

Chris, Shawn,

Our Environmental Services division prepared the attached Air Compliance Inspection Report at the Bridgeton Landfill in October 2012. This inspection was done at the request of our Air and Waste Management Division, Environmental Field Compliance Branch, pursuant to 40 CFR 60, Subpart WWW, Standards of Performance for Municipal Waste Landfills. They sampled for methane gas during the inspection. We are providing this report to MDNR for your information.

Sincerely,  
Daniel R. Gravatt, PG  
US EPA Region 7 SUPR/MOKS  
11201 Renner Boulevard, Lenexa, KS 66219  
Phone (913)-551-7324

Principles and integrity are expensive, but they are among the very few things worth having.

0714



30287581

Superfund

3.0

0102